


Pete & Jake's Hot Rod Parts • 401 Legend Lane • Peculiar, MO 64078 • 1-800-334-7240

# PETE & JAKE'S



• HOT ROD PARTS •



TO POSITION THE CROSS MEMBER, MAKE YOUR MEASUREMENT FROM THE COWL HOLE ON THE FRAME, FORWARD 28 1/2". THIS IS THE POSITION FROM CENTER OF THE AXLES POSITION IN THE FRAME. DEGREE THE CROSS MEMBER BACK, 5 TO 7° TACK, THEN CHECK ANGLE AGAIN AND THEN WHEELBASE. (112"). NOW MAKE YOUR FINAL WELD!